



Tungsten E Battery Replacement

Written By: Kathleen Hix



INTRODUCTION

This is a repair guide for battery replacement.



TOOLS:

- [iFixit Opening Tools](#) (1)
- [Spudger](#) (1)
- [T5 Torx Screwdriver](#) (1)



PARTS:


- [Double-Sided Tape](#) (1)
- [Tungsten E battery](#) (1)

Step 1 — Battery




- To reach the battery, follow steps 1 through 3 in the [Tungsten E Teardown](#)

Step 2



- Begin to pry up the battery. It is fastened to the mother board using two sided tape.
- ⚠ Caution: the battery is connected by two wires.


Step 3



- Remove the battery

⚠ Caution: Be careful not to tear the wires when removing battery.


Step 4



- Using a soldering iron, disconnect the battery wires.

ⓘ Note: the wires are soldered to the board.

Step 5



- Take replacement battery and solder the wires to the board.
- Take care to match wire colors as before.
- Use double sided tape to attach battery firmly to board.

To reassemble your device, follow these instructions in reverse order.

This document was last generated on 2017-06-18 08:04:22 AM.